

PORT ARANSAS HISTORIC RESOURCES SURVEY
PORT ARANSAS, NUECES COUNTY, TEXAS



HISTORIC RESOURCES INVENTORY

PRESERVATION CENTRAL, INC. FOR
THE PORT ARANSAS PRESERVATION AND HISTORICAL ASSOCIATION

December 2006

Port Aransas Historic Resources Survey, Nueces County, Texas

Inventory of Properties

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
123 S 10th Street	113	Low	1930	Building	Dwelling	Front Gable	Vertical Hardboard		porch altered, aluminum windows
			1965	Domestic	Dwelling		Good	1	
300 block S 10th Street	114	Low	1940	Building	Warehouse	Front Gable	Metal		cold storage
				Commercial	Vacant		Fair	1	
300 block S 10th Street	115	Low	1950	Building	Storage building	Flat	CMU		concrete warehouse/storage in trailer park
				Domestic	Storage building		Fair	1	
400 block S 10th Street	116	Medium	1930	Building	Vacation Cottages	Side Gable	Asbestos		Sea & Sand Cottages. address of office is 221 E. Ave. E, but that buidling (# 51) is a low priority and is not photographed
				Domestic	Vacation Cottages		Good	1	
404 S 10th Street	117	High	1930	Building	Dwelling	Cross Gable	Asbestos		original windows and entries, 4/4 windows, triangular knee braces
				Domestic	Dwelling	Craftsman	Good	1	
505? S 10th Street	118	Medium	1930	Building	Dwelling	Side Gable	Asbestos		has side porch
				Domestic	Dwelling		Good	1	
511 S 10th Street	119	High	1920	Building	Dwelling	Hip	Asbestos		hip porch on hip roof, 4/4 windows, exposed rafters, high integrity
				Domestic	Dwelling	Craftsman	Fair	1	
515 S 10th Street	120	Medium	1930	Building	Dwelling	Side Gable	Asbestos		louvered windows
				Domestic	Dwelling		Fair	1	
524 S 10th Street	122	Low	1955	Building	Dwelling	Flat	Stucco		flat roofed apartment in the yard of #123, but addressed differently
				Domestic	Dwelling		Good	1	
525 S 10th Street	121	Low	1935	Building	Dwelling	Side Gable	Wood		alterations, wood front deck
			1980	Domestic	Dwelling		Good	1	
526 S 10th Street	123	Medium	1930	Building	Dwelling	Front Gable	Vinyl		rustic porch posts and railing (replaced)
			1975	Domestic	Dwelling	Craftsman	Good	1	
100 block S 11th Street	90	Low	1960	Building	Dwelling	Side Gable	Asbestos		addressed on Ave. B but fronts 11th Street. multiple alterations, second story deck
				Domestic	Dwelling		Excellent	2	
100 block S 11th Street	142	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		paired 1/1 windows, rear addition
				Domestic	Dwelling	Minimal Traditional	Good	1	
200 S 11th Street	143	Low	1940	Building	Dwelling	Cross Gable	Asbestos		additions and alterations
			1970	Domestic	Dwelling		Good	1	
218 S 11th Street	144	Medium	1950	Building	Dwelling	Cross Gable	Asbestos		2 or more small houses?
				Domestic	Dwelling		Excellent	1	
227 S 11th Street	145	Medium	1940	Building	Dwelling	Side Gable	Stucco		replaced windows, triangle knee braces, stoop entry
				Domestic	Dwelling		Good	1	
100 block S 12th Street	99	Low	1955	Building	Dwelling	Hip	Asbestos/Wood		big addition on street side
			1975	Domestic	Dwelling		Fair	1	
129 S 12th Street	98	Medium	1955	Building	Dwelling	Front Gabled Bungalow	Wood		screened front gabled porch. address on 12th Street is a side entry; front of house faces Jill's Way
				Domestic	Dwelling		Good	1	
230 S 12th Street	96	Medium	1960	Building	Dwelling	Cross Gable	Asbestos		big picture windows
				Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
246 S 12th Street	95	Medium	1955	Building	Dwelling	Front Gable and Side Gable	Asbestos		two attached houses--larger, side-gabled house has two stories and a full screened porch on its upper story; front-gabled house has one story
			1975	Domestic	Dwelling		Good	2	
307 S 12th Street	97	Medium	1960	Building	Dwelling	Cross Hip	Asbestos		rambling; brick chimney
				Domestic	Dwelling	Ranch	Excellent	1	
400 block S 12th Street	165	Medium	1940	Building	Dwelling	Hip	Wood		Summer Place. 1- and 2-story sections, nice window trim, renovated, many new replacements. basement garage
			1995	Domestic	Dwelling	Prairie	Excellent	2	
500 block S 12th Street	94	Low	1960	Building	Dwelling	Hip	Asbestos		front addition and front porch addition
				Domestic	Dwelling		Good	2	
528 S 12th Street	93	Low	1960	Building	Dwelling	Hip	Wood		porch supported by poles
				Domestic	Dwelling		Fair	2	
500 block S 9th Street	112	Low	1930	Building	Dwelling	Flat	Asbestos		porch addition, roof flattened
			1960	Domestic	Retail		Fair	1	
519 S 9th Street	111	Medium	1925	Building	Dwelling	Front Gable	Masonite?		Victorian turned posts, piers not original, 1/1 windows
			2000	Domestic	Dwelling	Craftsman	Excellent	1	
100 block N Alister Street	109	Medium	1960	Building	Tourist Court	Flat	CMU		The Village
				Domestic	Multi-Unit Dwelling	Modern	Good	1	
104 N Alister Street	108	Medium	1925	Building	Dwelling	Cross Gable	Wood		small house turned office for Sportsman Lodge
			1932	Domestic	Office		Good	1	
115 N Alister Street	107	High	1954	Building	Retail	Complex	Wood/Metal		Billmore Hardware. still in use as hardware store. metal awning
			1970	Commercial	Retail		Good	1	
202 N Alister Street	106	Medium	1925	Building	Dwelling	Shotgun	Asbestos		now a tattoo parlor
				Domestic	Retail		Good	1	
300 block N Alister Street	5	Low	1955	Building	Dwelling	Side Gable	Asbestos		now a series of small shops
				Domestic	Retail		Good	1	
340 N Alister Street	8	High	1930	Building	Tourist Court	Side Gable	Wood		Gibbs Cottages. large 2-story building with hipped roof and a series of 1-story tourist cottages on the same lot.
				Domestic	Vacant	Craftsman	Good	2	
400 block N Alister Street	68	Medium	1949	Building	Community Center	Side Gable	Wood		community center. possible 1965 addition
			1965	Civic	Community Center		Good	1	
403 N Alister Street	2	Medium	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends
				Domestic	Vacant	Craftsman	Good	1	
403 B N Alister Street	3	Low	1935	Building	Dwelling	Front Gable	Asbestos		clipped gable
			1980	Domestic	Vacant	Craftsman	Fair	1	
403 C N Alister Street	4	Low	1935	Building	Dwelling	Front Gable	Asbestos		exposed rafter ends
			1985	Domestic	Retail	Craftsman	Good	1	
500 block N Alister Street	105	Medium	1960	Building	Auto Service	Flat	CMU		projecting awning, garage bays
				Commercial	Auto Service		Good	1	
100 block S Alister Street	40	High	1920	Building	Church	Complex	Hardiplank		original stained glass, turret
			1990	Religious	Church	Gothic	Excellent		
100 block S Avenue A	60	Low	1950	Building	Tourist Court	Flat	Asbestos		
				Domestic	Tourist Court		Fair	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
100 block S Avenue A	61	Low	1955	Building	Dwelling	Front Gable	Wood		front addition, louvered windows
			1980	Domestic	Dwelling		Good	1	
300 block E Avenue B	89	Low	1960	Building	Tourist Court	Shed	Asbestos		8 small apartments
				Domestic	Multi-Unit Dwelling		Fair	1	
319 E Avenue B	59	Low	1945	Building	Dwelling	Hip with Gable	Asbestos		1/1 windows, louvered blinds
				Domestic	Dwelling		Fair	1	
505 E Avenue B	58	Medium	1935	Building	Dwelling	Front Gable and Side Gable	Asbestos		two Bungalows stuck together
				Domestic	Dwelling		Excellent	1	
619 E Avenue B	57	Low	1935	Building	Dwelling	Cross Gable	Asbestos/Wood		fire victim. triangular knee braces, shuttered windows
				Domestic	Dwelling	Craftsman	Poor	1	
620 A E Avenue B	41 A	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		moved from the flats in 1938
				Domestic	Dwelling	Craftsman	Good	1	
620 B E Avenue B	41 B	High	1938	Building	Chapel	Pyramidal	Stucco		Carter Chapel/the Chapel on the Dunes. interior painted in the late 1970s by painter John Patrick Cobb. some recent minor alterations
				Religious	Chapel		Good	1	
639 A E Avenue B	42 A	Medium	1935	Building	Dwelling	Hip	Asbestos		windows replaced
			1990	Domestic	Dwelling	Craftsman	Excellent	1	
639 B E Avenue B	42 B	Medium	1930	Building	School	Front Gable	Asbestos		6/6 windows, exposed rafter ends. attached to #42 A
				Education	Dwelling	Craftsman	Good	1	
126 E Avenue C	44	Medium	1945	Building	Dwelling	Side Gable	Asbestos/Wood		aluminum windows, replaced door
				Domestic	Dwelling		Good	1	
225 E Avenue C	56	Medium	1935	Building	Dwelling	Front Gable	Asbestos		clipped gable, triangular knee braces, exposed rafter ends
			1970	Domestic	Dwelling	Craftsman	Good	1	
507 E Avenue C	55	Low	1955	Building	Dwelling	Front Gable	Asbestos		porch detracts
			1970	Domestic	Dwelling		Fair	1	
508 E Avenue C	43	Medium	1950	Building	Dwelling	Front Gable	Asbestos		louvered windows
				Domestic	Dwelling		Good	1	
603 E Avenue C	54	Medium	1955	Building	Dwelling	Cross Gable	Asbestos/Wood		paired windows
				Domestic	Dwelling		Good	1	
221 E Avenue E	51	Low	1955	Building	Dwelling	Front Gable	Wood		front and side additions
			1970	Domestic	Multi-unit Dwelling		Good	1	
309 E Avenue E	52	Low	1955	Building	Dwelling	Front Gable	Asbestos/Wood		faux bay window
			1980	Domestic	Dwelling		Good	1	
316 E Avenue E	91	Medium	1950	Building	Dwelling	Front Gable	Asbestos		side addition
				Domestic	Dwelling		Good	1	
107 E Avenue F	50	Medium	1955	Building	Vacation Cottages	Side Gable	Asbestos		duplex with full-face porch
				Domestic	Vacation Cottages		Good	1	
115 E Avenue F	49	Medium	1940	Building	Dwelling	Cross Gable	Wood		porch posts are 4x4s
			1985	Domestic	Dwelling	Craftsman	Good	1	
122 E Avenue F	46	Low	1955	Building	Dwelling	Side Gable	Wood		has addition and replaced wood
			1965	Domestic	Dwelling		Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
128 E Avenue F	47	Low	1955	Building	Dwelling	Side Gable	Wood		huge A-frame added
			1970	Domestic	Dwelling		Good	2	
131 E Avenue F	48	Medium	1950	Building	Dwelling	Cross Gable	Wood		cottage with 8/8 windows
				Domestic	Dwelling		Good	1	
200 block E Avenue F	92	Medium	1960	Building	Tourist Court	Flat	CMU		Deco concrete apartments
				Domestic	Multi-Unit Dwelling	Modern	Fair	1	
205 E Avenue F	110	Medium	1925	Building	Dwelling	Side Gable	Board and Batten		60s aluminum windows
			1960	Domestic	Dwelling		Fair	1	
415 E Avenue G	147	Medium	1960	Building	Vacation Cottages	Front Gable	Vertical Hardboard		paired 1/1 windows. Double Barr tourist cottages
				Domestic	Vacation Cottages		Good	1	
503 E Avenue G	146	Medium	1945	Building	Tourist Court	Flat	Hollow Tile		Laughing Horse tourist court
				Domestic	Tourist Court		Good	1	
603 E Avenue G	45	High	1940	Building	Tourist Court	Front Gable	Rock		Rock Cottages. 6/6 windows, honeycombed rock wth wide mortar joints
			1970	Domestic	Tourist Court	CCC	Good	1	
618 E Avenue G	166	Medium	1920	Building	Dwelling	Cross Gable	Wood		
			1970	Domestic	Multi-Unit Dwelling		Fair	1.5	
118 E Beach Street	85	Low	1960	Building	Dwelling	Hexagonal/Hip	Hardboard		possibly resurfaced
				Domestic	Vacant		Poor	1	
200 block E Beach Street	16	Low	1935	Building	Dwelling	Mansard	Wood		mansard front on front-gabled Bungalow with front-gabled porch
			1975	Domestic	Retail		Good	1	
208 E Beach Street	86	Low	1950	Building	Dwelling	Front Gable	Asbestos/Hardboard		enclosed porch with window display
			1965	Domestic	Retail		Good	1	
212 E Beach Street	87	Low	1960	Building	Unknown	Front Gable	Asbestos		infilled windows, replaced door
			1975	Civic	Vacant		Fair	1	
216? E Beach Street	88	Low	1945	Building	Dwelling	Front Gable	Wood		attached garage, aluminum replacement windows
				Domestic	Vacant		Poor	1	
229 B E Beach Street	17	Low	1960	Building	Dwelling	Front Gable	Wood		likely a manufactured home, paired 1/1
				Domestic	Dwelling		Fair	1	
200 block E Brown Avenue	102	Low	1975	Building	Dwelling	Front Gable	Hardboard		3 apartments; possibly originally a house with secondary dwelling or outbuilding?
				Domestic	Multi-Unit Dwelling		Excellent	1	
228 E Brown Avenue	101	Low	1940	Building	Dwelling	Cross Gable	Hardiplank		louvered windows and doors
			1960	Domestic	Dwelling		Good	1	
200 block E Brundrett Avenue	28	High	1960	Building	Church	Front Gable	Brick		good example of type; door protected
				Religious	Church	Modern	Excellent	1	
211 E Brundrett Avenue	29	Low	1960	Building	Dwelling	Hip	Asbestos		new metal roof, massive posts
				Domestic	Dwelling		Fair	2	
217 E Brundrett Avenue	30	High	1930	Building	Dwelling	Front Gable	Asbestos		very good example, louvered windows
				Domestic	Dwelling	Craftsman	Excellent	1	
224 E Brundrett Avenue	84	Medium	1935	Building	Dwelling	Hip	Asbestos		hip porch, 1/1 windows, exposed rafters
				Domestic	Dwelling	Craftsman	Good	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
128 A W Brundrett Avenue	24	Medium	1935	Building	Dwelling	Front Gable	Asbestos		4/1 and 1/1 windows, porch added or replaced circa 1960
			1960	Domestic	Dwelling	Craftsman	Good	1	
128 B W Brundrett Avenue	24 B	Medium	1935	Building	Garage	Front Gable	Asbestos		Hasp-hung door, multi-light windows
				Domestic	Vacant	Craftsman	Poor	1	
132 W Brundrett Avenue	25	Medium	1930	Building	Dwelling	Hip	Asbestos		hip with hip porch
				Domestic	Dwelling	Craftsman	Fair	1	
16 W Brundrett Avenue	26	Low	1930	Building	Dwelling	Side Gable	Asbestos		front-gabled porch
			1960	Domestic	Dwelling	Craftsman	Good	1	
17 W Brundrett Avenue	27	Low	1935	Building	Dwelling	Front Gable	Asbestos		enclosed porch
			1960	Domestic	Dwelling	Craftsman	Good	1	
320 E Channel View Drive	186	Low	1940	Building	Dwelling	Front Gable	Vertical Hardboard		1/1 windows, plain
				Domestic	Dwelling		Good	1	
326 E Channel View Drive	187	Medium	1940	Building	Dwelling	Front Gable	Asbestos		exposed rafter ends
			1970	Domestic	Dwelling	Craftsman	Fair	1	
327 E Channel View Drive	188	Low	1960	Building	Dwelling	Flat	Asbestos		no-frills "modern cottage"
				Domestic	Dwelling	Modern	Good	1	
410 E Channel View Drive	189	Low	1930	Building	Dwelling	Complex	Wood		initially a small Bungalow; big 1970s 2-story addition
			1975	Domestic	Dwelling	Craftsman/Contemporary	Good	2	
417 E Channel View Drive	192	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		1/1 windows, exposed rafter ends, brick chimney
				Domestic	Dwelling	Craftsman	Good	1	
624 E Channel View Drive	191	Medium	1955	Building	Dwelling	Side Gable	Asbestos		elevated, 2nd story porch
			1965	Domestic	Dwelling		Excellent	2	
732 E Channel View Drive	190	Medium	1955	Building	Dwelling	Side Gable	Asbestos		wide screened porches on both floors, upper floor deck added
			1965	Domestic	Dwelling		Excellent	2	
206 S Church Street	67	Medium	1960	Building	Dwelling	Cross Gable	Wood		louvered windows
				Domestic	Dwelling	Ranch	Good	1	
207 S Church Street	6	Medium	1930	Building	Dwelling	Front Gable	Vinyl		6/6 windows, no porch
			1985	Domestic	Dwelling	Craftsman	Good	1	
213 S Church Street	7	Medium	1935	Building	Dwelling	Front Gable	Asphalt		horizontal aluminum windows
			1965	Domestic	Dwelling		Good	1	
106 E Cotter Avenue	160	High	1920	Building	Retail	Cross Gable	Asbestos		The Big Kahuna restaurant. Picture windows. rare surviving historic commercial building
			1960	Commercial	Restaurant		Good	1	
200 E Cotter Avenue	161	High	1925	Building	Inn	Hip	Wood		Tarpon Inn. box columns, veranda. renovated. rare surviving historic inn--restaurant wing dates to 1904, main volume to 1925.
				Domestic	Inn	Classical/Craftsman	Excellent	2	
319 E Cotter Avenue	162	Low	1930	Building	Dwelling	Flat	Wood		replaced sliding windows
			1960	Domestic	Dwelling		Good	1	
326 E Cotter Avenue	163	Low	1930	Building	Dwelling	Side Gable	Wood		big addition on front side
			1980	Domestic	Dwelling		Good	1	
329 E Cotter Avenue	164	Low	1935	Building	Dwelling	Side Gable	Wood		clipped gable, big front additions
			1970	Domestic	Dwelling		Good	1	

Identification				Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials			
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories		
500 block E Cotter Avenue	175	Low	1935	Building	Dwelling	Front Gable	Asbestos		decks and additional 2nd-floor entry added	
			1965	Domestic	Dwelling	Craftsman	Good	2		
525 E Cotter Avenue	174	Medium	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends, 1/1 windows	
				Domestic	Dwelling	Craftsman	Good	1		
428 E Lantana Drive	167	Medium	1925	Building	Dwelling	Front Gabled Bungalow	Wood (false bevel)		turned porch posts are Folk Victorian	
			1995	Domestic	Dwelling	Craftsman	Excellent	1		
500 E Lantana Drive	168	Medium	1950	Building	Dwelling	Hip	Asbestos		shuttered windows, cupola, no porch	
			1980	Domestic	Dwelling	Prairie	Excellent	1		
513 E Lantana Drive	169	Medium	1930	Building	Dwelling	Cross Gable	Asbestos		porch with 4x4 posts added. Bungalow windows	
			1960	Domestic	Dwelling		Good	1		
518 E Lantana Drive	171	Medium	1960	Building	Dwelling	Flat	Asbestos/Wood		louvered windows. porch added	
				Domestic	Dwelling	Modern	Good	1		
523 E Lantana Drive	170	Low	1960	Building	Duplex	Side Gable	Asbestos/Wood		aluminum windows	
				Domestic	Duplex		Good	1		
400 block N Mercer Street	62	Low	1940	Building	Dwelling	Side Gable	Asbestos		multiple additions	
				Domestic	Dwelling		Fair	1		
407 N Mercer Street	39	Medium	1930	Building	Dwelling	Side Gable	Asbestos		clipped gables, dormers added	
			1975	Domestic	Dwelling	Craftsman	Fair	1.5		
442 N Mercer Street	63	Low	1955	Building	Dwelling	Side Gable	Asbestos		louvered doors and windows	
				Domestic	Dwelling		Fair	1		
509 N Mercer Street	38	Medium	1960	Building	Dwelling	Flat	Wood		casement and louvered windows	
				Domestic	Dwelling	Modern	Excellent	1		
203 E Oakes Avenue	36	Medium	1920	Building	Dwelling	Cross Gable	Wood (false bevel)		under renovation	
			2006	Domestic	Dwelling		Poor	1		
205 E Oakes Avenue	35	Low	1955	Building	Dwelling	Side Gable	Wood		big front addition and porch	
			1970	Domestic	Dwelling		Fair	1		
206 E Oakes Avenue	78	Low	1940	Building	Parsonage	Side Gable	Cement Stucco		may be a parsonage. in church yard (see #79)	
			1975	Religious	Parsonage		Good	1		
208 E Oakes Avenue	79	High	1915	Building	Church	Front Gable	Asbestos		St. Joseph's Catholic Church. now a residence.multi-light windows	
				Religious	Church	Gothic	Good	1.5		
209 E Oakes Avenue	34	Medium	1940	Building	Dwelling	Front Gable	Wood		late Bungalow. paired windows	
				Domestic	Dwelling		Good	1		
220 E Oakes Avenue	80	Low	1955	Building	Dwelling	Front Gable	CMU		main entry enclosed; entry stoop	
			1970	Domestic	Dwelling		Good	1		
221 E Oakes Avenue	33	Low	1930	Building	Dwelling	Hip	Asbestos		side front addition, louvered windows	
			1960	Domestic	Dwelling	Craftsman	Fair	1		
232 E Oakes Avenue	10	Medium	1930	Building	Dwelling	Cross Gable	Wood		clipped gable with clipped gable porch	
				Domestic	Dwelling	Craftsman	Good	1		
233 E Oakes Avenue	103	Low	1930	Building	Dwelling	Cross Hip	Hardboard		left half is hardboard	
			1950	Domestic	Dwelling		Good	1		

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
300 block E Oakes Avenue	81	High	1891	Site	Cemetery		Stone		Mercer Cemetery. about 7-8 headstones, some of which found when land leveled for school track.
				Funerary	Cemetery		Good		
320 E Oakes Avenue	82	Low	1930	Building	Dwelling	Side Gable	Wood		aluminum windows; porch enclosed
			1965	Domestic	Dwelling		Fair	1.5	
321 E Oakes Avenue	32	Low	1935	Building	Dwelling	Cross Gable	Asbestos		enclosed porch, front addition
			1960	Domestic	Dwelling	Craftsman	Good	1	
322 E Oakes Avenue	83	Low	1940	Building	Dwelling	Front Gable	Stucco		aluminum windows; exposed rafters
			1965	Domestic	Dwelling		Fair	1	
325 E Oakes Avenue	31	High	1930	Building	Dwelling	Cross Gable	Asbestos		paired windows
				Domestic	Dwelling	Tudor Revival	Excellent	1	
124 W Oakes Avenue	37	Low	1940	Building	Dwelling	Front Gable	Wood/CMU		Bungalow with hipped addition
			1950	Domestic	Commercial		Fair	1	
125? W Oakes Avenue	77	Low	1955	Building	Dwelling	Cross Gable	Wood		shiplap siding, aluminum windows replaced
			1970	Domestic	Dwelling		Good	1	
200 block N Oleander Street	69	Low	1960	Building	Tourist Court	Side Gable	Wood		tourist court or tourist apartments
				Domestic	Tourist Court		Fair	1	
218 N Oleander Street	70	Low	1935	Building	Dwelling	Hip	Aluminum		big side addition
			1970	Domestic	Dwelling		Fair	1	
600 block N Oleander Street	104	Medium	1925	Building	Retail	Side Gable	Wood		Brundrett Taxidermy, porch supported by driftwood
				Commercial	Retail		Fair	2	
200 block S Oleander Street	1	High	1915	Building	Dwelling	Side Gable	Wood (false bevel)		Sears house. low gables, hipped dormer, high integrity
			1980	Domestic	Vacant	Classical/Colonial Revival	Good	1.5	
400 block E Palm Drive	173	Low	1935	Building	Dwelling	Side Gable	Asbestos		exposed rafters, big carport added
			1965	Domestic	Dwelling		Fair	1	
432 E Palm Drive	172	Medium	1935	Building	Dwelling	Cross Gable	Wood/Vertical Hardboard		louvered windows, exposed rafter ends, triangular knee braces
			1965	Domestic	Dwelling	Craftsman	Good	1	
106 E Roberts Avenue	100	Medium	1950	Building	Retail	Front Gable with Parapet	Wood		parapet likely new
			1995	Commercial	Retail		Good	1	
200 E Roberts Avenue	66	Medium	1935	Building	Dwelling	Hip with Gable	Asbestos		gabled porch, louvered windows
				Domestic	Dwelling	Craftsman	Good	1	
207 E Roberts Avenue	22	Medium	1945	Building	Dwelling	Hip with Gables	Asbestos		louvered windows, entry porch
				Domestic	Dwelling		Excellent	1	
219 E Roberts Avenue	21	Medium	1930	Building	Dwelling	Front Gable	Wood/Hardboard		aluminum windows, porch enclosed
			1960	Domestic	Dwelling		Fair	1	
224 E Roberts Avenue	75	Low	1940	Building	Dwelling	Side Gable	Asbestos		paired windows, screened porch
			1960	Domestic	Dwelling		Good	1	
227 E Roberts Avenue	20	Medium	1960	Building	Dwelling	Front Gable	Wood/Hardboard		aluminum windows
				Domestic	Dwelling		Good	1	
230 E Roberts Avenue	76	Low	1945	Building	Dwelling	Front Gable	Asbestos		scrollwork porch post "capitals," new windows
			2000	Domestic	Dwelling	Craftsman/Folk Victorian	Excellent	1	

Identification			Date	Classification					Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
317 E Roberts Avenue	18	Medium	1960	Building	Dwelling	Front Gable	CMU		decorative wood in gable end
				Domestic	Dwelling		Good	1	
319? E Roberts Avenue	19	Low	1940	Building	Dwelling	Front Gable	Wood		multiple additions
			1960	Domestic	Dwelling		Fair	1	
100 block W Roberts Avenue	72	Medium	1930	Building	Dwelling	Cross Hip	Asbestos		new roof
			1995	Domestic	Dwelling		Good	1	
113 W Roberts Avenue	74	Medium	1935	Building	Dwelling	Side Gable	Wood		front deck, triangular knee braces on stoop porch roof
				Domestic	Dwelling		Good	1	
119 W Roberts Avenue	73	Medium	1930	Building	Dwelling	Cross Gable	Asbestos		exposed rafter ends, original screens
				Domestic	Dwelling	Craftsman	Good	1	
141 W Roberts Avenue	71	Medium	1935	Building	Dwelling	Side Gable	Asbestos		paired 1/1 windows, stoop porch
				Domestic	Dwelling		Good	1	
146 W Roberts Avenue	23	Medium	1935	Building	Dwelling	Cross Hip	Asbestos		paired 1/1 windows, screened porch
				Domestic	Dwelling		Fair	1	
300 block N Station Street	9	Medium	1955	Building	Dwelling	Front Gable	CMU/Wood		may be part of Lister's Cottages. paired 1/1, decorative wood gable
				Domestic	Dwelling		Good	1	
300 block N Station Street	65	Low	1940	Building	Dwelling	Cross Gable	Asbestos		replaced windows and door
				Domestic	Dwelling	Craftsman	Poor	1	
400 block N Station Street	11	Low	1930	Building	Dwelling	Front Gable	Asbestos		1/1 paired, exposed rafter ends, has matching shed
				Domestic	Vacant	Craftsman	Poor	1	
438 N Station Street	64	Low	1955	Building	Dwelling	Front Gable	Asbestos		replaced windows, lattice porch
				Domestic	Dwelling		Fair	1	
503 N Station Street	12	Medium	1955	Building	Dwelling	Front Gable	Asbestos		side addition, aluminum windows
			1965	Domestic	Dwelling		Good	1	
507 N Station Street	13	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		cross-hip roof, replaced porch, louvered window
			1965	Domestic	Dwelling	Craftsman	Good	1	
515 N Station Street	15	Low	1950	Building	Dwelling	Front Gable	Vinyl		replaced windows, 4x4 posts
				Domestic	Dwelling		Fair	1	
611 N Station Street	14	Medium	1935	Building	Dwelling	Cross Gable	Asbestos		originally a hipped porch, paired windows
				Domestic	Dwelling	Craftsman	Good	1	
109 S Station Street	141	Low	1960	Building	Dwelling	Flat	Asbestos		typical example
				Domestic	Dwelling		Fair	1	
208 A? S Station Street	140 A	Low	1945	Building	Dwelling	Side Gable	Asbestos		front house; see #s 140B and 140C
				Domestic	Dwelling		Good	1	
208 B? S Station Street	140 B	Medium	1930	Building	Dwelling	Front Gable	Wood		house behind #140A
				Domestic	Dwelling		Fair	1	
208 C? S Station Street	140 C	Low	1930	Building	Garage	Front Gable	Wood?		garage with wood shingles; see #s 140A & 140B
				Domestic	Garage		Poor	1	
211? S Station Street	138	Low	1940	Building	Dwelling	Side Gable	Vertical Hardboard		late Bungalow
				Domestic	Dwelling		Good	1	

Identification			Date	Classification						Notes
Address	Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials			
Resource Name/Designation Type			Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories		
215 S Station Street	139	Low	1940	Building	Dwelling	Front Gable	Asbestos/Brick		altered Bungalow	
			1960	Domestic	Dwelling		Good	1		
312 S Station Street	137	Medium	1930	Building	Dwelling	Side Gable	Asbestos		exposed rafters, 1/1 and 6/6 windows	
				Domestic	Dwelling	Craftsman	Fair	1		
318 S Station Street	136	Medium	1930	Building	Dwelling	Side Gable	Asbestos		exposed rafter ends	
				Domestic	Dwelling	Craftsman	Fair	1		
412 A S Station Street	133	High	1935	Building	Dwelling	Cross Gable	Asbestos		paired 1/1 windows, high integrity	
				Domestic	Dwelling	Craftsman	Good	1		
412 B S Station Street	134	Medium	1930	Building	Dwelling	Side Gabled Bungalow	Wood		could be new, metal roof, new windows	
			2000	Domestic	Dwelling	Craftsman	Excellent	1		
414 B? S Station Street	135 B	Low	1935	Building	Dwelling	Side Gable	Unknown		hidden behind #135	
				Domestic	Dwelling		Fair	1		
414? S Station Street	135	Medium	1930	Building	Dwelling	Cross Gable	Wood		entry porch, replaced door, louvered windows	
				Domestic	Dwelling	Craftsman	Good	1		
418 S Station Street	132	Medium	1935	Building	Dwelling	Front Gable	Vertical Hardboard		paired 1/1 windows	
			1950	Domestic	Dwelling		Fair	1		
500 block S Station Street	128	Medium	1935	Building	Dwelling	Side Gable	Aluminum?		couldn't see properly to photograph	
				Domestic	Dwelling		Good	1		
501? S Station Street	131	Low	1940	Building	Dwelling	Front Gable	Wood/Hardboard		porches and added decoration detract	
			1990	Domestic	Dwelling		Good	1		
506 S Station Street	129	Low	1940	Building	Dwelling	Front Gable	Asbestos		multiple additions, pergola detracts	
			2000	Domestic	Dwelling		Good	1		
507 S Station Street	130	Medium	1935	Building	Dwelling	Front Gable	Wood (false bevel)		clipped gable, windows changed	
			1970	Domestic	Dwelling	Craftsman	Good	1		
522 S Station Street	127	Medium	1940	Building	Dwelling	Side Gable	Vinyl		louvered windows	
			1990	Domestic	Dwelling		Excellent	1		
600 block S Station Street	125	Low	1940	Building	Dwelling	Side Gable	Vinyl		has long addition	
			1995	Domestic	Dwelling		Excellent	1		
603? S Station Street	126	Medium	1930	Building	Dwelling	Side Gable	Asbestos		small cottage with 1/1 windows	
				Domestic	Dwelling		Fair	1		
604 S Station Street	124	Medium	1940	Building	Dwelling	Flat	Asbestos		paired 6/6 windows, upper story porch with rustic posts and railing	
			1975	Domestic	Dwelling	Craftsman	Good	2		
322 E Tarrant Avenue	185	Medium	1940	Building	Dwelling	Side Gable	Wood/Screen		exposed rafters, long screened porch	
			1960	Domestic	Dwelling		Good	1		
401 E Tarrant Avenue	183	Low	1935	Building	Dwelling	Front Gable	Wood		big picture window added, windows replaced, likely moved to site	
			1975	Domestic	Dwelling	Craftsman	Good	1		
402 E Tarrant Avenue	184	Low	1945	Building	Dwelling	Side Gable	Wood/CMU		multiple additions	
			1960	Domestic	Dwelling		Fair	1		
413 E Tarrant Avenue	182	Low	1980	Building	Dwelling	Front Gable	Vertical Hardboard		possibly 1980s with historic references. hipped porch, shuttered windows	
				Domestic	Dwelling		Good	1		

Identification				Date	Classification					Notes
Address		Field ID	Priority	Original	Resource Type	Historic Use	Plan Type/Roof Form	Exterior Materials		
Resource Name/Designation Type				Altered	Property Type	Current Use	Stylistic Influence	Condition	# of Stories	
419 E Tarrant Avenue		181	Low	1945	Building	Dwelling	Front Gable	Wood?		altered windows
					Domestic	Dwelling		Good	1	
612 E Tarrant Avenue		180	Medium	1940	Building	Dwelling	Hip	Asbestos		elevated, louvered windows
					Domestic	Dwelling	Craftsman	Good	2	
622 E Tarrant Avenue		179	Medium	1935	Building	Dwelling	Hip	Asbestos		cross hip, elevated, 1/1 windows
				1960	Domestic	Dwelling	Craftsman	Good	2	
700 block E Tarrant Avenue		177	Medium	1960	Building	Dwelling	Side Gable	Wood/Asbestos/Brick		house has angled section, roof flares at gable ends, aluminum windows
					Domestic	Dwelling	Modern	Good	2	
706 E Tarrant Avenue		178	Medium	1940	Building	Dwelling	Hip	Asbestos		elevated over garage, 1/1 windows, deck added
				1960	Domestic	Dwelling	Craftsman	Good	2	
747 E Tarrant Avenue		176	Medium	1935	Building	Dwelling	Hip	Asbestos		elevated over garage, paired and tripled windows, exposed rafter ends
				1960	Domestic	Dwelling	Craftsman	Good	2	
324 S Trojan Street		149	Medium	1930	Building	Dwelling	Front Gable	Asbestos		1-story house with 2-story addition on rear. 1/1 windows
				1970	Domestic	Dwelling	Craftsman	Good	1	
424 S Trojan Street		148	Low	1950	Building	Dwelling	Cross Gable	Asbestos		raised onto posts, windows replaced
				1965	Domestic	Dweling	Craftsman	Good	2	
100 E White Avenue		193	Medium	1935	Building	Grocery	Front Gable			Souvenir City, originally Loomis (Gaulding) Grocery, damaged by Hurricane Celia in 1970; renovated/altered in 1970s.
				1975	Commercial	Retail		Good	1	
200 block E White Avenue		154	Low	1960	Building	Dwelling	Hip	Wood		on stilts, horizontal aluminum windows
					Domestic	Dwelling		Good	2	
218 E White Avenue		153	Low	1930	Building	Dwelling	Front Gable	Wood/Hardboard		1-story with 2-story addition
				1995	Domestic	Dwelling		Good	1	
300 block E White Avenue		155	Low	1930	Building	Dwelling	Hip	Asbestos/Wood		has large front and side addition
				1965	Domestic	Dwelling		Good	1	
300 block E White Avenue		157	Medium	1920	Building	Dwelling	Pyramidal	Wood (false bevel)		exposed rafter ends
				1970	Domestic	Dwelling	Craftsman	Poor	1	
312 E White Avenue		156	Low	1955	Building	Dwelling	Side Gable	Asbestos		
					Domestic	Dwelling		Good	1	
403 E White Avenue		158	Medium	1940	Building	Dwelling	Cross Gable	Vinyl		louvered windows
				1975	Domestic	Dwelling		Good	1	
420 E White Avenue		159	Medium	1930	Building	Dwelling	Front Gable	Aluminum		louvered windows
				1965	Domestic	Dwelling		Good	1	
100 block W White Avenue		151	Low	1940	Building	Dwelling	Hip	Asbestos		roof changed
					Domestic	Dwelling		Fair	1	
12 W White Avenue		152	Medium	1950	Building	Dwelling	Front Gable	Asbestos		1/1 windows, picture window
					Domestic	Dwelling		Good	1	
128 W White Avenue		150	Medium	1940	Building	Dwelling	Cross Gable	Asbestos		windows replaced
					Domestic	Dwelling		Good	1	